MDM 5000 DIRECT DRIVE MOTOR SET ORDERING INFORMATION

P XXX X XX X XX XXX

STATOR/ROTOR
PARTS SET

Stator OD In mm

Winding Stack
(1 = One stack
2 = Two stack
3 = Three stack
4 = Four stack
5 = Five stack
6 = 6 stack
S = Special)

Winding letter followed by a digit
For example,
40 V/Krpm = C0
45 V/Krpm = D5 (i.e., D=50-5 = 45)
43 V/Krpm = D7 (i.e., D=50-7 = 43)

N = No Thermal protection
T = Thermistor
S = Thermostat
K = Special

NN = No Halls
HA = Hall Commutation

Special requirements
(Specify)